

Environmental Impact
Statement
for the
Salem to Manchester
Corridor

Freeway Level of Service

Node	LOS
MA State Line to Exit 1	F
Exit 1 to Exit 2	F
Exit 2 to Exit 3	F
Exit 3 to Exit 4	Е

Ramp Junction Level of Service


Node	LOS	
	AM	PM
1A	В	F
1B	С	F
1C	F	Е
1D	F	F
2A	С	F
2B	В	F
2C/2D (weave)	F	F
3A	В	F
3B	В	F
3C	F	С
3D	F	С

Signalized Intersection Level of Service

Node	LOS	
Node	AM	PM
1	В	В
2	В	D
3	D	F
4	С	E
5	С	С
7	E	F*
8	Е	Е

Unsignalized Intersection Level of Service

	Node	LOS	
		AM	PM
	6	F	F



Vanasse Hangen Brustlin, Inc.

Figure 4.2-3 Level of Service Summary 2020 No Build Conditions Sheet 1 of 2